

Preliminary Information

PIT5558 Person Outside of Vehicle May Hear a Faint Beep Noise in the Background During Lengthy Bluetooth Phone Conversations

Models

Brand:	Ma	doli	Model Years:	VIN:		Engine:	Transmissions:	
	Model:		Model Years:	from	to			
Chevrolet	Equinox		2016 - 2017	All	All	All	All	
GMC	Terrain		2016 - 2017	All	All	All	All	
Involved Region or Country:		North America						
Additional RPO/s:		UP9						
		during blo This usua happenin	uetooth phone conversations ally occurs 5 or more minutes g about once per second. If t ersation, but will obviously be	but everyth into the con his beep is l	ing sou versation heard, it	nds normal to the on, starting as an o is normally very fa	occasional beep and eventually aint and does not interfere with	
Condition:		Copy and paste this link into the web browser to hear the concern. http://sandyblogs.com/techlink/wp-content/uploads/2017/03/03-Voice-012.m4a						
		If this concern is reported, evaluate bluetooth and radio performance to ensure that no other complaints exist. If other complaints are verified, this PI does not apply. If this concern exists or is reported but can't be verified, do not replace any parts as engineering is currently evaluating the concern. Please document all available details on the repair order describing the concern, type of phone, phone software version, phone network, etc. and ask the customer to keep their phone updated with the latest software.						
Cause:		GM Engineering is investing the concern						

Warranty Information

Labor Operation:	Description:	Labor Time:
3480518*	Check for codes and evaluate bluetooth operation	.3 hr
	*This is a unique labor operation for bulletin use only.	

Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is currently evaluating this concern. This PI will be updated with additional details as they become available.

Version History

Version	1
Modified	
Wodilled	

