



Preliminary Information

PIT5447B Buzz / Rattle Noise From Dash Or Front Of Vehicle

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade	2015 - 2017	All	All	All	All
Chevrolet	Suburban	2015 - 2017	All	All	All	All
Chevrolet	Tahoe	2015 - 2017	All	All	All	All
GMC	Yukon	2015 - 2017	All	All	All	All

Supersession Statement

This PI was superseded to add 2017 Model Year. Please discard PIT5447A.


The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Some customers may comment that they hear a rattle or buzz noise from the dash or front of the vehicle. It may be most noticeable with engine RPM or when turning left or right.

Recommendations / Instructions

Inspect for the rear heater pipes contacting the passenger side exhaust manifold. If the rear heater pipe is found to be contacting the exhaust manifold (as shown below), reposition the heater pipe so it no longer makes contact.



Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4480348 *	Reposition The Rear Heater Pipe	0.4 hr.
* This is a unique labor operation for bulletin use only.		

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

