



# Preliminary Information

## PIT5420C Water Rush Or Gurgle Noise From Heater Core

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2015 - 2017	All	All	LCV	All
GMC	Canyon	2015 - 2017	All	All	LCV	All

### Supersession Statement

This PI was superseded to update to include the 2017 MY section. Please discard PIT5420B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition / Concern

The customer may note a water rush or gurgle type noise from the center dash area.  
The technician may isolate this noise to the heater core caused by air in the cooling system.

### Recommendations / Instructions

Inspect the system for coolant leaks and proper coolant level.  
No other repairs are to be performed at this time. Engineering is currently validating a repair for release as a field fix.  
PI will be updated or bulletin will be released when more information is available.  
Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

