

Engine Coolant Level Above MAX Mark on Arriving Vehicle? It's OK!

AFFECTED VEHICLES

2017 NSX

EDITOR'S NOTE: This article replaces the one posted in **March 2017** to extend the article's shelf life. The issue(s) covered are still being addressed.

To improve efficiency, the factory has installed new equipment for filling the engine coolant system, which cuts down on the amount of engine run time. As a result, the engine coolant level may be above the **MAX** mark on the reserve tank when the vehicle leaves the factory.

If you're seeing this on an arriving vehicle, don't try to adjust the coolant level; it's OK where it is. The coolant level will return to normal (between the **MIN** and **MAX** marks) over time as the vehicle is driven.