



# Preliminary Information

## PIC6182B High Voltage Battery Disconnect Relay Fuse Open Or Blown

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2016 - 2017	All	All	L3A	MKV

### Supersession Statement

This PI was superseded to update Part Information. Please discard PIC6182A.

#### Supersession Statement

This PI was superseded to update Part Information. Please discard PIC6182A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition / Concern

During diagnosis you may find that one of the fuses in the High Voltage Battery Disconnect Relay assembly is Open Or Blown. Previously, some of the fuses were not available from SPO and were only available through the Warranty Parts Center (WPC).

### Recommendations / Instructions

All the replacement fuses for the High Voltage Battery Disconnect Relay Assembly are now available through GM SPO parts. It is no longer necessary to contact the WPC.

### Parts Information

Model Year	Part Number	Part Name	Qty
2016-2017 Volt	24278480	10 Amp Fuse - HEATER	1
2016-2017 Volt	24278473	15 Amp Fuse - OBCM	1
2016-2017 Volt	24278474	30 Amp Fuse - CHCM	1
2016-2017 Volt	24278475	40 Amp Fuse - ACCM	1

### Warranty Information

For vehicle repaired under warranty use:

Labor Operation	Description	Labor Time
5031780	High Voltage Battery Disconnect Relay Fuse Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

