

## DTC P0562 Set with MIL Off and No Apparent Symptom?

### AFFECTED VEHICLES

2017 MDX Sport Hybrid and 2017 NSX

While running an all DTC check with the i-HDS, are you seeing DTC P0562 (battery condition monitor module power source circuit unexpected voltage) with no other DTCs listed, yet the MIL is off and there's no apparent symptom? If so, chances are there's nothing wrong with the vehicle. Just clear the DTC, and recheck by cycling the ignition **three** times.

If the DTC doesn't come back, the vehicle is OK. But if it does, along with one or more **other** DTCs, then continue with normal system troubleshooting, starting with the other DTC(s) first.