



Mitsubishi Motors North America, Inc.

6400 Katella Avenue
Cypress, CA 90630
Telephone: 714-372-6000
www.mitsubishicars.com

Date: August 18, 2017

**To: All US Salt Belt State Mitsubishi Dealer Principals
All US Salt Belt State Mitsubishi Dealership Service Managers
All US Salt Belt State Mitsubishi Dealership Parts Managers**

**Subject: Temporary investigation of Supplemental Restraint System (SRS) Front Impact Sensors –
Investigation Concluded**

Since August 2016, Mitsubishi Motors North America, Inc. (MMNA) has been conducting a temporary investigation of Supplemental Restraint System (SRS) front impact sensors on the following vehicles:

- 2008 – 2015 MY Lancer (including RALLIART editions)
- 2009 – 2015 MY Lancer Sportback (including RALLIART editions)
- 2008 – 2015 MY Lancer Evolution

Today, August 18, 2017, MMNA announces the conclusion of this temporary investigation. Dealers are no longer required to collect impact sensor(s) for investigation, and replacement of non-accident related failure of SRS front impact sensor(s) on one of the above vehicles must again follow normal warranty policy. Dealers can no longer replace affected sensor(s) regardless of time and mileage.

Thank you for your assistance through this temporary investigation. If you have any questions, please contact your MMNA District Parts and Service Manager.

Sincerely,

MMNA Fixed Operations