



Preliminary Information

PIT5316A Chrome Center Cap Coming Off Or Missing On Chrome Or Polished Aluminum Wheels

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500/3500	2015 - 2017	All	All	All	All
GMC	Sierra 2500/3500	2015 - 2017	All	All	All	All

Equipped with Chrome or Polished Aluminum Wheels (RPO PHF, PYR, PYS, PYU, PYV, Q7R, RQ9, RT4 S90)

Supersession Statement:

This PI was superseded to add model years. Please discard PIT5316.

Condition / Concern

Dealer may report the center caps on chrome or polished aluminum wheels are missing or came off while driving.

Recommendations / Instructions

In an effort to prevent this situation, be sure to press the chrome center cap onto the wheel until an audible “click” is heard. Then, perform a pull test to verify the cap is secure. The cap should NOT come off with hand pressure, rather, it should take a tool (i.e. trim stick) to remove the cap.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

