



Preliminary Information

PIC6282A Vibration Moan Noise Heard At less than 1500 RPM Or The Air Conditioning Blowing Warm Air

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2016 - 2017	SOP	Built Before April 24, 2017	1.5 LFV, 1.8 LKN	All
Involved Region or Country		North America				
Condition		<ul style="list-style-type: none">A customer may comment that there is a vibration or moan type noise heard while driving. <p>This is present usually at lower engine RPMs (less than 1500). The noise may change as the A/C compressor is engaged or disengaged. The moan noise sounds like it's coming from the engine compartment area.</p> <ul style="list-style-type: none">Air Conditioning is blowing warm air. <p>Inspect the air conditioning compressor hose for being fractured in the elbow portion of the low side line where it attaches to the compressor.</p>				
Cause		A/C compressor bracket mounting bolts are loose.				

Correction:
Tighten both of the A/C compressor bracket mounting bolts to 22 Nm (16 lb. ft.).
Replace the air conditioning compressor hose if it is fractured.

Warranty Information

Labor Operation	Description	Labor Time
4417120	Air Conditioning Compressor Replacement	Use Published Labor Operation Time

Version History

Version	2
Modified	6/12/2017 Update Title Condition and Correction