

Temperature Control Dial Won't Set to Maximum Cool

AFFECTED VEHICLES

2016–17 Fit and 2016–17 HR-V LX

Can't set the temperature control dial to maximum cool? We're aware of this issue, and we currently have it under investigation.

Until we come up with a solution, for now, replace the heater unit.

© 2017 American Honda Motor Co., Inc. – All Rights Reserved