

HONDA Tech Line Summary Article

September 2017 ATS 170802 Version 2

Navigation Screen Clock Reads 00:00

AFFECTED VEHICLES

2000-04 Odyssey and 2003-05 Pilot

EDITOR'S NOTE: This article replaces the one posted in **August 2017**.

Is the navigation screen clock reading **00:00**? We're aware of this issue and have it under investigation.

For 2000-03 Odysseys and 2003 Pilots that didn't have the navigation maps updated with software Version 2.1x to 2.Ax, this issue self-corrected on September 17, 2017, and the clock reads normally. For 2004 Odysseys, 2004–05 Pilots, and 2000-03 Odysseys that **did** have the navigation maps updated with that software version, this issue remains and the clock reads 00:00.

We're currently working on a software patch to fix this.

© 2017 American Honda Motor Co., Inc. - All Rights Reserved