

## Replacement FC Ion Exchanger Filter Element in Short Supply

### AFFECTED VEHICLES

2017 Clarity Fuel Cell

In a Code A maintenance service, you must replace the FC ion exchanger filter element. Right now, that filter element is in short supply, but we expect to have it back in stock soon.

Until then, if you get a vehicle in for a Code A maintenance service, order a replacement filter element. Then, do the rest of the specified maintenance items, and return the vehicle to your customer. Make sure your customer knows it's OK to drive the vehicle until the filter element can be replaced.