


Temperature Sensor Connector in Replacement IMA Battery Now Different

AFFECTED VEHICLES

2005–07 Accord Hybrid

If you're replacing the IMA battery, be aware the 6-pin temperature sensor connector in the replacement battery is different than before. It now uses just **four** of the terminals instead of all six.



But don't worry; this won't cause any problems. Just install the IMA battery like you normally would, and update the software if needed.