



Technical Service Bulletin

23 TDI Generation III 2.0L Phase 1 Emissions Modification - Repair Authorization

23 17 38 2045801/1 January 11, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3	2015	All	2.0 liter TDI

Technical Background

Audi of America is requesting your cooperation in supplying us with technical information related to the repair process for vehicles on which the TDI Generation III 2.0L Phase 1 Emissions Modification is being performed, "Campaign 23T4". Audi will use this information to ensure prompt analysis and resolution of any emerging concerns.

TDI Generation III 2.0L Phase 1 Emissions Modification has been released for repairs.

Service

If you experience any issues while performing "Campaign 23T4", or after the software update for the TDI Generation III 2.0L Phase 1 Emissions Modification, follow the process below to open a Technical Assistance Center (TAC) ticket.

Note:

TAC authorization is not required to perform the software update; it is only required if an issue occurs while the update is being performed (for example, if update fails, SVM will not update control modules, etc.) or if an issue occurs after the software update.

If an issue is experienced during the software update:

- Create a phone or web contact in the TAC system. Select concern group "Campaign-TDI Emissions Concerns".



- Contact TAC for further instructions. Be sure to record the TAC case number on the repair order.
- After the concern is corrected, findings must be reported before the TAC ticket can be closed.



Technical Service Bulletin

Note:

Issues related to ODIS should be directed to the ODIS Diagnostic Support Group at 888.896.1298, along with a feedback via the ODIS tool (refer to document AOS-15-03 for ODIS feedback set-up instructions). ODIS issues will still be reviewed as part of the TDI Monitoring Program.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2045801) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.