



Technical Service Bulletin

90 Outside temperature display in instrument cluster is incorrect

90 17 74 2046346/2 January 6, 2017. Supersedes Technical Service Bulletin Group 90 number 16-73 dated December 22, 2016 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2016 - 2017	All	Analog Instrument Cluster

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header data (Corrected Elsa display issue)
1	12/22/2016	Initial publication

Complaint about the outside temperature display in the instrument cluster. The analog instrument clusters (PR numbers 9S7 and 9S5) are affected.

- After a longer stationary period the outside temperature display in the instrument cluster may show temperatures around 32.0°F (0.0°C) although it is clearly warmer.

Technical Background

Incorrect software.

Production Solution

Optimized software version 0361.



Technical Service Bulletin

Service

SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions.*
2. Update the Instrument Cluster Control Module (J285) (address word 0017) using the SVM action code as listed in the table below if necessary:

Model	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Code Input
A4	8W5920740	<0339	8W5920740	0361	TPKWW361B9

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	9025		
Damage Code:	0039		
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 70 TU)
	Road test prior to service procedure	No allowance	00 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2046346/2		



Technical Service Bulletin

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2046346) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.