

[Next Unread Message](#)**View Message**

Sent on	10	13	2017	Expires on	10	27	2017
From	Parts and Service Division						
Subject	Request for Visit: 2017 NSX Wind Noise (Zone 2)						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
 From: Technical Research & Support Group
 RE: Request for Visit: 2017 NSX Wind Noise (Zone 2)

**This message is solely directed to Acura dealership personnel; please handle accordingly.
 Print this i/N message and provide a copy to the Shop Foreman and all Service Consultants.**

Background

American Honda Motor Co., Inc. (AHM) is investigating certain 2017 NSXs with a client complaint of excessive wind noise while driving. To fully understand the cause of this condition, AHM would like to inspect the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. VIN must be after 19UNC1...HY000515.
2. Must be able to duplicate the issue.
3. Vehicle has not been involved in a collision.
4. No repair has been attempted for this issue.

Action Required

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.