



Technical Service Bulletin

PSS 46 Brake Noise

46 17 65 2046986/1 February 24, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017 - 2018	All	Not Applicable

Condition

Customer may report hearing a squeal noise from front brakes in the following conditions:

When:	After vehicle was parked for several hours/overnight, and usually in reverse
Speed:	Below 15 mph
Temperature:	Below 60°F



Tip: For an example of the sound, see video located at: <http://audi-external.kzoplatform.com/swf/player/333>.



Figure 1. QR code.



Technical Service Bulletin

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

Explain to the Customer that a solution is forthcoming and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.

Create a PSS record in the PSS application via the Pending Service Solutions link in AccessAudi (under Related Links>>Service), or through the Technical Assistance page in ELSA.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2046986) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.