

9003787 09/27/2017 MY17 WD

GPOP - Issue Review System

Part Number: 68276627A\$, 68276628A\$, 68276625A\$, 68276626A\$, 68276639A\$, 68276640A\$, 68276623A\$

Part Description: RH and LH Exhaust Resonators

Issue Description: If replacing resonator due to alignment issues between exhaust tips and rear fascia, please call the Design Release Engineer Spencer Hayes at cell (517) 215-0520 to review. If no response in 15 minutes, proceed with repair. Please take pictures of the issue and email to caitlin.feltner@fcagroup.com.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~