



Preliminary Information

PIT5544A Normal Characteristic - Hydraulic Rush Noise from Power Steering Gear

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado2500/3500	2016 - 2018	All	All	All	All
GMC	Sierra2500/3500	2016 - 2018	All	All	All	All
Involved Region or Country	North America					
Additional Options (RPO)	NV8					
Condition	Some customers may comment on a hydraulic rush or flow type noise from the power steering gear. This noise is a characteristic of the new Active Hydraulic Assist System RPO NV8 and no repairs should be made. The noise is most noticeable in the cab at idle, in park, with all accessories turned off.					

Version History

Version	2
Modified	10/13/2017 Updated Model Years

