



Preliminary Information

PIT5574C Fuel Gauge Will Not Go To Full

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2018	All	All	All	All
GMC	Terrain	2018	All	All	All	All

Involved Region or Country:	North America
Additional RPO/s:	None
Condition:	After fueling vehicle fuel gauge does not go to full.
Cause:	Fuel module not properly seating in the bottom of the tank.

Correction:

Engineering is working on a field fix for this concern , this communication will be updated when more information is available.

Version History

Version	4
Modified	7-24-2017 Updated Repair information
	10/24/2017 Updated to advise Engineering is further investigating.
	10/30/2017 Updated to add 2018 GMC Terrain

