

INTEROFFICE MEMORANDUM

Original Publication Date: October 19, 2017

To: All Toyota Region and Private Distributor General Managers / Vice Presidents

From: Bob Waltz 
Group Vice-President, Product Quality and Service Support

Subject: Limited Service Campaign H0T – **Remedy Notice**
Certain 2018 Model Year Camry Vehicles
Rear Wheel Arch Sealer Gap

Specific information for Region support is provided below.

Condition

In the subject vehicles, the inner portion of the right rear fender arch may have an improper sealer application. In these vehicles, water and salt may enter and cause rust spots, paint blistering, or perforation of the rear fender arch. This condition is most likely to occur in areas with heavy road salt application.

Dealer Notification

The attached dealer letter will be sent to all Toyota dealers on October 19, 2017.

Please reference the attached Dealer Letter for additional details.

Please review this notification with your staff to assure that all relevant personnel have been briefed regarding this subject.

Thank you for your cooperation.