



GENUINE MOTOR PARTS AND MOTOR ACCESSORIES BULLETIN



PAB1062

2017-01-26

PAB1062: SCREAMIN' EAGLE MILWAUKEE-EIGHT STAGE IV KIT PART DESCRIPTION ERROR

Purpose

- To notify Dealers using Talon and Lightspeed that the recently launched Milwaukee-Eight Stage IV kit part descriptions are incorrect in their DMS.

Summary and Parts Affected

The newly introduced Milwaukee-Eight Stage IV performance kits below were listed incorrectly in the January price file, as a result, they will show up with inaccurate descriptions in your Talon or Lightspeed DMS.

All other sources of product information are accurate (ie; New Product Catalog, New Product Introduction sheet, and H-Dnet.com).

Below is the accurate and updated information for the new kits:

- **92500060** - KIT,SE STAGE IV 107-114,BLK,TWIN-COOLED
- **92500062** - KIT,SE STAGE IV 107-114,BLK,OIL-COOLED
- **9 2 5 0 0 0 6 4** - KIT,SE STAGE IV
114-117,GRAN.TWIN-COOLED

Your DMS system will be updated with the release of the next price file, which is anticipated on 2/13/17.

Action Required

- Verify that the kit you are ordering is correct for the intended application using the above product information prior to placing any orders.

Questions

Please contact Technical Service with any concerns regarding application. Please direct all other questions to your Dealer Services Representative.

Draft

