

Reference	SSM73527
Models	Discovery / L462 Range Rover Velar / L560
Title	Poor Air Conditioning (A/C) Performance
Category	Electrical
Last modified	07-Sep-2017 00:00:00
Symptom	208000 Climate Control

ContentIssue:

A customer may express a concern of one or more of the following symptoms:

- Cycling vent temperatures, blowing warm and then cold.
- Misting up of the front, side or rear screen(s) in cool ambient air temperatures (less than 15°C)
- Poor cooling performance of the Air Conditioning (A/C) system
- Warm, damp or musty smells coming from the vents

Cause:

A/C compressor electronic control sticking.

Action:

In order to clear any blockage in the valve, a flushing routine has been developed which will run after engine off. The function will cycle the valve for 10seconds starting 60 seconds after engine stop.

Update the HVAC Control Module using Pathfinder release 95 or later

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.