



## 2018 Tiguan



Volkswagen

Engine	Part	Part Number	Quantity
<b>2.0L Turbo: CCTA</b>	Oil Filter	06K 115 562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	4.7L (4.9qt)
	Drain Plug Gasket	N 911 679 01	1
	Air Filter	1K0 129 620 D	1

Miscellaneous	Part	Part Number	Quantity
<b>Miscellaneous</b>	Pollen Filter (odor and allergen filter)	1K1 819 669	1
	Pollen Filter (filter insert with odor and harmful substance filtering)	1K1 819 653 B	1
	Pollen Filter (dust and pollen filter element)	1K1 819 644 B	1
	Wiper Blades – Set	5N1 998 002	1
	Wiper Blade – Rear	6Q6 955 425 A	1
	Battery (Amp. Req. Vary)	000 915 105 *	1

Engine	Part	Part Number	Quantity
<b>2.0L Turbo: DGUA</b>	Oil Filter	06K 115 562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	5.7L (6.0qt)
	Drain Plug Gasket	06L 103 801	1
	Air Filter	5Q0 129 620 B	1

Miscellaneous	Part	Part Number	Quantity
<b>Miscellaneous</b>	Pollen Filter w/o Electronic HVAC Regulation (20K Only)	5Q0 819 644 A	1
	Pollen Filter with Electronic HVAC Regulation (20K Only)	5Q0 819 669	1
	Front Wiper Blade (Left)	5NN 955 425	1
	Front Wiper Blade (Right)	5NN 955 426	1
	Rear Wiper Blade (335 mm)	5NN 955 427	1
	Battery (Amp. Req. Vary)	000 915 105 *	
	Battery (Amp. Req. Vary)	5K0 915 105 *	1

**\*VIN Required**

© 2017 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

## 2018 Tiguan Service Reminder Reset

### Resetting the service reminder display

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the service reminder can be reset as follows:

- Switch off the ignition.
- Press and hold the **0.0** button in the instrument cluster.
- Switch on the ignition.
- Release the **0.0** button.
- One after the other, the following messages appear in the display:

**Reset oil service?**

**Do you really want to reset  
inspection?**

- When you see the message for the interval you want to reset (either oil change or inspection), confirm the request by pressing the **0.0** button in the instrument cluster. A confirmation message appears in the display when the service reminder has been reset.



Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

**For current fluid capacity charts, please refer to the Maintenance section in Elsa.**