



# Preliminary Information

PIT5601 Not Able to Display Side by Side View of Speed Limit Icon Next to Digital Speedometer on the Driver Information Center

## Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2017	All	All	All	All
GMC	Canyon	2017	All	All	All	All
Involved Region or Country:		North America				
Additional RPO/s:		I06				
Condition:		Not Able to Display Side by Side View of Speed Limit Icon Next to Digital Speedometer on the Driver Information Center				
Cause:		Engineering is investigating				

## Correction:

If this concern is encountered, check for DTCs and diagnose/repair them as necessary. If no DTCs are present, do not attempt any repairs or replace parts in an attempt to enable this feature as engineering is currently evaluating this concern.

## Warranty Information

Labor Operation:	Description:	Labor Time:
3480728	Check For DTC's and Evaluate DIC Operation	.3 hours

## Version History

Version	1.0
Modified	

