

**MODEL:** Karma Revero

**DATE:** December 2017

**TITLE:** Front Dome Light Replacement

**First Release**

**PRIORITY:** On Complaint

**APPLICABILITY:** MY17 and MY18 Revero

**MARKET REGION:** North America

**PURPOSE:** Replace the front dome light on complaint of flicker

The front dome light may exhibit a brief flicker when switched on, on the opposite side light. For example, when pressing left button, the left light will turn on and the right side will flicker.

Confirm the flicker is present from the dome light.

If present then continue with the bulletin, if this is *not* found no further action needs to be taken.

Disconnect the 12V system.

Remove and replace the dome light assembly with the newest updated component as follows.

Remove the bezel, by gently pulling off by hand. install is the reverse by placing it and pushing firmly up to engage and fasten.

Remove the now exposed Phillips head screws. Install torque is 2.0 +/- 0.5 Nm



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

**MODEL: Karma Revero****DATE: December 2017****TITLE: Front Dome Light Replacement****First Release**

Lower the dome lamp.  
disconnect the connector in the  
headliner, and replace with the new unit.



Disconnect the dome lamp connector from the  
headliner harness.

Replace with the new dome light assembly as  
indicated. Install is the reverse of removal.

Reconnect the 12V system and verify operation of  
the installed light assembly.



To match color code of the dome light assembly to the interior see SC-17-01-05



# Technical Service Bulletin

**TB-17-82-17**

**MODEL:** Karma Revero

**DATE:** December 2017

**First Release**

**TITLE:** Front Dome Light Replacement

**PARTS REQUIRED:**

PART NUMBER	DESCRIPTION
C131146701006CC (or higher index)	Console Assembly - Overhead

**SHOP SUPPLIES:**

DESCRIPTION
N/A

**SPECIAL TOOLS:**

DESCRIPTION
N/A

**CAUSAL PART:**

PART NUMBER	DESCRIPTION
C131197501002	Front Dome Light

**LABOR CODES:**

CODE	DESCRIPTION	TIME	DEFECT CODE
90-50-01-01	Dome Light R&R	0.3	90-50-01-01

**SUBLET:**

CODE	DESCRIPTION	AMOUNT
N/A		

**WARRANTY DISPOSITION:** This repair is covered under the New Vehicle Limited Warranty, in effect for five (5) years from the in-service date with no mileage limitation.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.