

SSM 46908	Some 2018 F-150 vehicles with less than 300 miles on the odometer may exhibit 0 percentage oil life remaining or change oil now message in the message center after PCM reprogramming or a KAM reset. Allow PCM to completely shut down by turning ignition to off state for at least 5 minutes. Engineering is investigating, monitor OASIS for updates. To assist with investigation, refer to the Professional Technician Society (PTS) website and use the report a vehicle concern link at the bottom of the OASIS report.
--------------	---