



Carpet edge is vertical,  
end of carpet can be seen



Top edge of carpet has entered the kinematic causing  
stall



Carpet is turned back on its self, results in bulge and  
miss fit