



# Technical Service Bulletin

---

## 44 Tire wear, Goodyear Eagle 285/45 R20 All Season

44 17 66 2048563/1 August 17, 2017.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017 - 2018	All	Goodyear Eagle tires

## Condition

The tire has abnormal wear on the outer edges. The tire pressure and the alignment are according to specifications.

## Technical Background

High ambient temperatures in connection with rough roads lead to increase wear only on the outer edges of the tire.

The following photograph shows an irregularity on the outer side and on the inner side of the tire (Figure 1). For this specific type of concern the tire must be replaced.



# Technical Service Bulletin

---



**Figure 1.** Irregularity on the outer side and on the inner side of the tire.

The following photograph shows a normal condition and the tire cannot be replaced.



# Technical Service Bulletin

---



**Figure 2.** Normal condition.

## Production Solution

Not applicable.

## Service

If:

- The remaining tread depth is above 6.5mm (8/32<sup>nds</sup>" )
- Wear on outer/inner edges is the same as Figure 1, then proceed as follows:
  1. Replace all 4 tires with:
    - *Pirelli Scorpion Verde 285/45 R20 112 H XL AOE.*
  2. Upload pictures of the tires to DOC-IT for claim validation (4 pictures: one for each tire with visible marks FL, FR, RL, and RR).
  3. Submit tires through Warranty Claim Portal on Dealer Tire website >> Workmanship and Materials >> tearing of tread.



# Technical Service Bulletin

4. If tires are similar to Figure 2, do not replace the tires and proceed with tire rotation.



**Tip:** Perform the repair only if the Customer concern is clearly confirmed, otherwise the claim will be debited.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• 110 up to 12 Months/12,000 Miles.</li> <li>• If vehicle is outside any warranty this Technical Bulletin is information only.</li> </ul>		
<b>Service Number:</b>	4440		
<b>Damage Code:</b>	0010		
<b>Labor Operations:</b>	Check tread depth and wear on all tires (upload pictures to DOC-IT)	4440 9999	25 TU
	Remove 2 front wheels + tires	4405 2000	30 TU
	Remove 2 rear wheels + tires	4405 2000	30 TU
	Replace 2 front tires	4440 5650	50 TU
	Replace 2 rear tires	4440 5650	50 TU
<b>Diagnostic Time:</b>	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
<b>Claim Comment:</b>	As per TSB #2048563/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



# Technical Service Bulletin

---

## Required Parts and Tools

Part Number	Part Description	Quantity
DT2398500 (Contact Dealer Tire)	Pirelli Scorpion Verde 285/45 R20 112 H XL AOE	04 (If necessary)

## Additional Information

All parts and service references provided in this TSB (2048563) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.