

Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat	2015-2017	1.8T	09G AQ250	All	All
		CPKA/CPRA	Automatic		
Jetta	2015-2017	1.8T	09G AQ250	All	All
		CPKA/CPRA	Automatic		
Beetle / Beetle Convertible	2015-2017	1.8T	09G AQ250	All	All
		CPKA/CPRA	Automatic		
Golf / Golf Sportwagen	2015-2017	1.8T	09G AQ250	All	All
		СХВВ	Automatic		
Tiguan	2015-2017	All	09M AQ450	All	All
<u> </u>	-		Automatic		

Condition

00 17 03 February 3, 2017 2043858 Supersedes V011603 dated April 26[,] 2016 to include MY2017 and update text.

Suspect Oil Leak at Bell Housing

Diagnosing fluid leaks near engine rear main seal/transmission bell housing:

Customer states there is a red/yellow/gold colored fluid leaking from the engine/bell housing area.

Technical Background

Due to the use of rust inhibitor/anti-seize products during transmission assembly/transportation, these fluids can wash out of the transmission bell housing over time causing a customer concern of engine/transmission fluid leak. This technical bulletin is intended to inform you of the use of these production products and assist with identifying this concern.

Production Solution

Information only.

© 2017 Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Bulletin

Service

If the fluid from the transmission bell housing is not red the transmission is not leaking Automatic Transmission Fluid (ATF) as both the 09G AQ250 and 09M AQ450 gearbox fluid is red in color.

If ATF is found, please take a picture and contact the Volkswagen Technician Helpline for further assistance if transmission replacement is necessary.

Warranty

Information only.

Required Parts and Tools

Information only.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

Document Control Revision Table						
Instance Number	Published Date	Version Number	Reason For Update			
2043858/3	2/3/17	V001703	Additional model year applicability.			
2043858/1	4/26/16	V001603	Original publication.			

© 2017 Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.