



Countries: CANADA, UNITED STATES **Document ID:** IK1201396
Availability: ISIS, FleetISIS, IsSIR **Revision:** 0
Major System: ENGINES **Created:** 9/29/2017
Current Language: English **Last Modified:** 10/26/2017
Other Languages: NONE **Author:** Amber Chapman
Viewed: 55

[Less Info](#)

Hide Details

Coding Information

| | | | | | | | |
|----------------------|-------------------------------|--|-----------------------------|------------------|-----------------------------|-------------------------|-----------------------------|
| Copy Link | Copy Relative Link | Bookmark View My Bookmarks | Add to Favorites | Print | Provide Feedback | Helpful 2 | Not Helpful 0 |
|----------------------|-------------------------------|--|-----------------------------|------------------|-----------------------------|-------------------------|-----------------------------|

Title: LT / RH with A26 Cold Start option

Applies To: LT and RH with A26

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

10/26/2017 - Initial Article Release

DESCRIPTION

This document will provide information on the optional A26 Cold Start System.

SYMPTOM(s)

Customer Observations or Concerns: The optional Cold Start Assist feature is not present.

SERVICE INFORMATION

Please see [Did You Know Letter HPU-060](#) for more information.

OTHER RESOURCES

[Master Service Information Site](#)

Hide Details

Feedback Information

Viewed: 54
Helpful: 2
Not Helpful: 0

No Feedback Found