


---

**INTEROFFICE MEMORANDUM**

Original Publication Date: October 5, 2017

To: All Toyota Region and Private Distributor General Managers / Vice Presidents

From: Bob Waltz   
Group Vice-President, Product Quality and Service Support

Subject: Special Service Campaign H0P – **Remedy Notice**  
Certain 2017 Model Year Yaris Vehicles  
Instrument Panel Wire Harness

---

**Specific information for Region support is provided below.**

**Condition**

In the subject vehicles, an incorrect instrument panel wire harness may have been installed during the vehicle assembly process. The incorrect instrument panel wire harness may not be compatible with the Pre-Collision system front sensor. As a result, the Automatic High Beam and Pre-Collision system may be inoperative.

**Dealer Notification**

The attached Dealer Letter will be sent to all Toyota dealers on October 5, 2017 at approximately 3:00 PM Central Time.

***Please reference the attached Dealer Letter for additional details.***

Please review this notification with your staff to assure that all relevant personnel have been briefed regarding this subject.

Thank you for your cooperation.