



## 2018 Tiguan

| Engine           | Part   | Part Number   | Quantity     |
|------------------|--|---------------|--------------|
| 2.0L Turbo: DGUA | Oil Filter   | 06K 115 562   | 1            |
|                  | VW 508 00, VW 504 00*<br>or VW 502 00*<br>Use synthetic oil SAE 0W-20* | N/A           | 5.7L (6.0qt) |
|                  | Drain Plug Gasket  | 06L 103 801   | 1            |
|                  | Air Filter   | 5Q0 129 620 B | 1            |

| Miscellaneous | Part   | Part Number   | Quantity |
|---------------|--|---------------|----------|
| Miscellaneous | Pollen Filter w/o Electronic HVAC Regulation (20K Only)  | 5Q0 819 644 A | 1        |
|               | Pollen Filter with Electronic HVAC Regulation (20K Only) | 5Q0 819 669   | 1        |
|               | Front Wiper Blade (Left)                                 | 5NN 955 425   | 1        |
|               | Front Wiper Blade (Right)                                | 5NN 955 426   | 1        |
|               | Rear Wiper Blade (335 mm)                                | 5NN 955 427   | 1        |
|               | Battery (Amp. Req. Vary)                                 | 000 915 105** |          |
|               | Battery (Amp. Req. Vary)                                 | 5K0 915 105** | 1        |

<sup>\*</sup>If you must add oil and no oil is available that meets the Volkswagen oil quality standard required for your engine, you can add a maximum 0.5 liters (0.5 qt.) of engine oil that meets the ACEA A3/B4 and API SN specification, and has a viscosity grade of SAE 0W-20.

Using oil with a different viscosity grade than the SAE 0W-20 can cause the vehicle emissions and fuel consumption to increase. Only use different oils in cases of emergency.

<sup>\*\*</sup>VIN Required

## 2018 Tiguan Service Reminder Reset

## Resetting the service reminder display

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the service reminder can be reset as follows:

- Switch off the ignition.
- Press and hold the 0.0 button in the instrument cluster.
- · Switch on the ignition.
- Release the 0.0 button.
- One after the other, the following messages appear in the display:

Reset oil service?

Do you really want to reset inspection?

• When you see the message for the interval you want to reset (either oil change or inspection), confirm the request by pressing the  $\boxed{0.0}$  button in the instrument cluster. A confirmation message appears in the display when the service reminder has been reset.



Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

For current fluid capacity charts, please refer to the Maintenance section in Elsa.