



Volkswagen

# Service Information

**Support**

**Number: VSS-17-14**

**Subject: TDI "Campaign 23V6"  
3.0L Emissions Modification – Gen 2.1**

**Date: Nov 10, 2017**

**Dealers: U.S.**

To prevent damage to the EGT sensor 4 during the AEM, **DO NOT** use a hammer and punch, heat, air hammer, etc. Sensor damage may result from heat, impact, or vibration. **Utilize hand tools only, including using the exhaust stud press tool for stud removal.** Please see VSE-17-20 about obtaining a loaner press tool. If the tool is not available, a brake clevis pin puller (OTC 5057) can be used and is available in the aftermarket.