



Service Bulletin

File in Section: -

Bulletin No.: 17-NA-324

Date: October, 2017

INFORMATION

Subject: Information on P80 Lubricant for Front Stabilizer Shaft

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT6	2016	2018				

Involved Region or Country	North America and N.A. Export Regions
-----------------------------------	---------------------------------------

The purpose of this bulletin is to inform dealership technicians that a P80 lubricant, GM P/N 19354433 (In Canada, P/N 19354434), is available and **REQUIRED** for any repairs that involve the removal of the front stabilizer shaft. The Front Stabilizer Shaft Replacement procedure in SI has been updated to reflect this change.

Version	1
Modified	Released October 10, 2017

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**