



Service Bulletin

File in Section: -


Bulletin No.: 17-NA-247

Date: October, 2017

INFORMATION

Subject: Information on Traces of EGR Cooler Housing Actuator Exhaust Residue Seen in Colder Climates

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Cruze	2017	2018			Diesel (RPO LH7)	
	Equinox	2018	2018				
GMC	Terrain	2018	2018				

Involved Region or Country	North America
Condition	 <p style="text-align: right;">4841052</p> <p>Some customers may comment that exhaust residue (2) can be seen condensing onto the aluminum housing of the EGR assembly, making it appear as if the bypass actuator arm seal (1) has failed.</p>
Information	<p>Note: Do Not replace the EGR assembly for this condition.</p> <p>This is normal operation and will not affect the function of the EGR cooler assembly.</p>

Parts Information

No parts are required for this repair.

Version	2
Modified	October 11, 2017 – Added the 2018 Model Year to Cruze and added the Equinox, Terrain models.

