



SERVICE CAMPAIGN

Rider's Manual

HP4 RACE (K60)

Leadership circle

Marketing

Sale
New motorcycles

Sale
Used motorcycles

Aftersales

Administration

Service Information No. 01 001 17

Service Information No. 01 001 17

SERVICE CAMPAIGN Rider's Manual HP4 RACE (K60)

Details

In the course of quality checks at BMW Motorrad, it has been determined that in the case of the HP4 RACE model, rider's manuals have been supplied which do not contain the complete maintenance schedule. The maintenance work "Replacing the steering tube" at 10000 km is missing.



Figure: Title page of the rider's manual

Series solution

As of 08/29/2017, the correct rider's manuals are being supplied for the series produced vehicles.

Service Solution

The rider's manuals must be renewed for the affected motor vehicles **before delivery**. In the case of vehicles that have already been delivered, the rider's manual must be sent to the customers.

Warranty processing

Defect code

00 01 01 00 00	Renewing rider's manual
----------------	-------------------------

FRU number

00 60 226	Replacing Rider's manual, 3 FRUs
-----------	----------------------------------

Part Number

01 40 8 406 647	Rider's manual (US English)
-----------------	-----------------------------

Questions regarding this bulletin?

For technical inquiries in relation to this bulletin	Please contact the PuMA team
For warranty inquiries in relation to this bulletin.	Submit an IDS ticket to the Warranty Department
For parts inquiries in relation to this bulletin	Adam.Sacher@bmwnaext.com
Motorcycle Service and Technical Manager	Gordon.McDonnell@bmwna.com
Bulletin authored/published by	Gery.Torok@bmwna.com