



# Preliminary Information

## PIT5581 Rear HVAC Blows Warm

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Envision	2016 - 2017	All	All	All	All
Involved Region or Country:		North America				
Additional RPO/s:		CJ4				
Condition:		Rear HVAC Blows Warm Air.				
Cause:		Possible broken auxiliary temperature door.				

### Service Procedure:

Engineering advises to inspect for a possible broken Auxiliary Temperature Door , DO NOT order / replace the Temperature Actuator for this concern.

### Version History

Version	1.0
Modified	

