



# Preliminary Information


PIC6273 Shifter assembly missing cover for BTSI - cover is serviceable do not replace entire assembly

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore	2013 - 2017	All	All	All	All
Chevrolet	Trax	2013 - 2017	All	All	All	All
Involved Region or Country	North America					
Additional Options (RPO)	N/A					
Condition	The BTSI cover is missing					
Cause	The BTSI cover may be missing or may break when removing the cover to test the shift interlock solenoid.					

Correction:  
Do not replace the transmission shift control. The BTSI override cover is serviceable.  
#1 in first image is missing BTSI cover and second image is call out in the parts catalog.





Parts Information

Description	Part Number	Qty
(Buick Encore) Bezel Jet Black	95417955	1
(Buick Encore) Bezel Piano black	42355599	1
(Chevrolet Trax) Bezel Black	42559687	1
(Chevrolet Trax) Bezel Platinum	95417953	1

Version History

Version	1
Modified	