

**Subject: Engineering Information – Malfunction Indicator Lamp (MIL) On, DTCs P0171 Fuel Trim System Lean Bank 1 and/or P0174 Fuel Trim System Lean Bank 2**

*This PI has been revised to end the need for information from the field. Please discard PIE0433.*

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2014	2018			LLT, LFY or LFX	All
Chevrolet	Traverse	2014	2018				
Chevrolet	Equinox	2014	2017				
GMC	Acadia	2014	2018				
GMC	Terrain	2014	2017				

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.