

**Subject: Engineering Information – Key Fob/Transmitter Inoperative**

*This PI has been revised to end the need for information from the field. Please discard PIE0396A.*

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Impala	2017	2018			All	All

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.