

Subject: Engineering Information – Noise Originating from Front Shock/Strut While Traveling at Low Speeds and/or Going Over Bumps

This PI has been revised to end the need for information from the field. Please discard PIE0397.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado	2017	2017			All	All
GMC	Sierra	2017	2017			All	All

If you encounter a vehicle with the above condition, refer to the latest version of PIT5533 for further instructions.