

Subject		Market	
Entune Apps Inoperative With iOS 11.2 Device USB Tethered		USA	
Service Category		Section	
Audio/Visual/Telematics		Navigation/Multi Info Display	
Applicability			
All Applicable Models			

APPLICABLE VEHICLES

2018	Camry	2018	Sienna
2018	Camry HV		

CONDITION

Some customers may experience an inoperative Entune™ Apps Suite after connecting an Apple device with iOS version 11.2 or later via USB tethering.

RECOMMENDATIONS

Advise the customer to disconnect the device from the USB and only use Bluetooth to use the Entune™ App suite.

Note: Scout moving maps will not be available when connecting via Bluetooth.

LINK REFERENCES

This Tech Tip does not contain any link references