



SI B16 01 17
Fuel Supply Systems

February 2017
Technical Service

DELIVERY STOP: ACTIVATED CHARCOAL FILTER

MODEL

F25 (X3)	F26 (X4)
----------	----------

SITUATION

A Delivery Stop has been issued on the BMW X3 and X4 produced from February 3, 2017 – February 7, 2017 involving the activated charcoal filter and holding bracket. The filter and the bracket must be inspected for cracks and replaced if necessary.

Approximately 333 vehicles affected by this stop are in dealer inventory. Vehicles which are affected will show the campaign as “Open” when checked either in AIR or ISPA Next. Once the Warranty Vehicle Inquiry system is updated on Saturday, February 25, 2017 it will display the same information. The affected vehicles will be identified with the campaign description:

STOP012094 B160117 Activated Charcoal Filter.

This bulletin will be updated with repair instructions and warranty information as soon as they become available.

For your convenience, a VIN list of affected vehicles is attached.

ATTACHMENTS

View PDF attachment [B160117 Delivery Stop Legal.](#)

View PDF attachment [B160117 VIN List.](#)

[Copyright ©2017 BMW of North America, Inc.]