



Telematics Device Spares Replacement Part Activation via DCSnet for BMW Assist

UPDATE! What's New:

- **Model:** All models added along with 6AC option code
- **Situation:** All information added
- **Information:** Deleted CDMA related information and added activation of Wi-Fi control unit
- **Procedure:** Added “Note” regarding ConnectedDrive support hotline information

New information provided by this revision is preceded by this symbol **UPDATE!**.

This Service Information bulletin supersedes SI B84 03 11 **dated September 2012**.

UPDATE! MODEL

E90 (3 Series Sedan)	E91 (3 Series Sports Wagon)	E92 (3 Series Coupe)	E93 (3 Series Convertible)
E70 (X5)	E71 (X6)	E82 (1 Series Coupe)	E84 (X1)
E88 (1 Series Convertible)	E89 (Z4)	F01, F02 (7 Series Sedan)	F02H, F04H (7 Series ActiveHybrid)
F06 (6 Series Gran Coupe)	F07 (5 Series Gran Turismo)	F10 (5 Series Sedan)	F10H (5 Series ActiveHybrid)
F12 (6 Series Convertible)	F13 (6 Series Coupe)	F15 (X5)	F16 (X6)
F22 (2 Series Coupe)	F23 (2 Series Convertible)	F25 (X3)	F26 (X4)
F30 (3 Series)	F31 (3 Series)	F32 (4 Series)	F33 (4 Series)

Sedan)	Sports Wagon)	Coupe)	Convertible)
F34 (3 Series Gran Turismo)	F36 (4 Series Gran Coupe)	F30H (3 Series ActiveHybrid)	F48 (X1)
F80 (M3 Sedan)	F82 (M4 Coupe)	F83 (M4 Convertible)	F85 (X5 M)
F86 (X6 M)	I01 (i3 & i3 REX)	I12 (i8)	G12 (7 Series Sedan)
G30 (5 Series Sedan)	F87 (M2 Coupe)		

UPDATE! Equipped with one of the following BMW Assist option code(s): 639 or 6NL or 6AC

UPDATE! SITUATION

A replacement telematics control unit must **only** be activated for vehicles with an active BMW Assist subscription.

Note: 2G CDMA and 2G GSM telematics control units cannot be activated because they are no longer supported and the supporting network(s) have been decommissioned.

UPDATE! INFORMATION

The following changes have taken place:

- All Telematics control unit replacements must be activated by Part managers via the DCSnet application.
- New steps included in the procedure for activating Telematics control unit replacements for vehicles equipped with Wi-Fi Hotspot (6WD).

UPDATE! PROCEDURE

Please refer to the attachment for the **updated** instructions on Telematics control unit replacement parts activation via DCSnet.

All Telematics control unit replacements are to be activated by the Parts manager before release to the technician for installation in the vehicle with an active BMW Assist subscription.



Note: For questions or assistance with this process, please contact the ConnectedDrive

Production Support Hotline at (201) 307-4347 or CDHotline@bmwna.com

UPDATE! WARRANTY INFORMATION

Not applicable.

ATTACHMENTS

View PDF attachment [Telematics Control Unit Replacement Part Activation Guide](#).

[Copyright ©2017 BMW of North America, Inc.]