

Subject

HV Battery Cooling System Filter Maintenance

Market

USA

Service Category

Vehicle Interior

Section

Meter/Gauge/Display

Applicability

All Hybrid Models

APPLICABLE VEHICLES

2016-2018	RAV4 HV	2010-2018	Prius
2013-2018	Avalon HV	2010, 2012-2015	Prius PHV
2012-2018	Prius V	2017-2018	Prius Prime
2012-2018	Prius C	2012-2018	Highlander HV
2011-2018	Camry HV		

CONDITION

Some Customers may complain about a Hybrid Vehicle Battery cooling system warning message. This warning message may appear when the HV Battery cooling system loses efficiency due to debris on the filter and or some object obstructing the air inlet.

COOLING PERFORMANCE
OF THE HYBRID
BATTERY IS LOW
CONSULT A DEALER



or

Maintenance Required
for Hybrid Battery
Cooling Parts
at Your Dealer

RECOMMENDATIONS

It is suggested to:

1. Clean the HV Battery cooling system filter every 5K miles
2. Keep the HV Battery cooling system air inlet area free of debris such as towels or paper

LINK REFERENCES

1. [HYBRID / BATTERY CONTROL: BATTERY COOLING FILTER: INSPECTION; 2016 - 2017 MY Prius \[11/2015 - ???????\]](#)