



Preliminary Information

PIP5518A Rattle Or Pop Noise During Gas Engine Start

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2016 - 2018	All	All	1.5L L3A	All
Involved Region or Country	North America					
Additional Options (RPO)	None					
Condition	Rattle Or Pop Noise During Gas Engine Start					
Cause	Under Investigation At This Time.					

Correction:

Some customers may have a concern of a rattle or pop noise during gas engine start. This concern only occurs on low speed tip in type maneuvers. It would normally be duplicated during stop go traffic type of situations where the engine starts in the 2000 rpm range. This issue will not occur on zero vehicle speed starts or during high pedal input starts.

If no codes or other symptoms are present, do not attempt repairs at this time.

Advise the customer that GM Powertrain is aware of this concern and working on a resolution.

The cause of the noise is understood.

This issue will not cause any damage to the propulsion or vehicle systems.

Version History

Version	2
	9/15/2017 – Updated Correction Section.

