



# Preliminary Information

PIP4723C Website for AFIT, TPM, GR8, MIT, PICO Scope and VDR Updates

## Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
All	All	1995 - 2017	All	All	All	All

## Supersession Statement

This PI was superseded to include additional details regarding VDR, TPMS, MIT, GR8, PICO Scope and AFIT software updates and also updated the website path due to recent changes. Please discard PIP4723B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

## Condition / Concern

If you need to download or update the AFIT, TPM, GR8, MIT, PICO Scope or VDR tools, follow the steps below:

1. Log into GM global connect.
2. Click on the "Departments" dropdown menu and select "Service".
3. Under "Applications" on the service page, select "Special Tools and Software updates".
4. You will now be re-directed to [www.gmtoolsandequipment.com](http://www.gmtoolsandequipment.com) (do not access this site directly as it requires the use of Global connect to allow downloads)
5. Click the link under "Software Downloads" for the latest AFIT, TPM, GR8, MIT, PICO Scope or VDR software version and a new page will open.
6. Click the setup links and follow instructions to update the tool.

**Notice:** The VDR should be updated with the latest software and programmed correctly before it is installed in a customer's vehicle for a snapshot. The VDR software version number is listed at the top of the screen when the VDR program is opened.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

