



## Technical Tip

<b>Topic</b>	74-15-02TT – Passenger Side Heated Seat May Take Longer to Heat Up and Potentially be Lower in Temperature
<b>Market area</b>	United States 444 Volkswagen of America, Inc. (6444)
<b>Brand</b>	Volkswagen
<b>Date</b>	June 27, 2017

## Condition

<b>ATTENTION:</b>
<b>THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.</b>
<b>TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.</b>

### Passenger Side Heated Seat May Take Longer to Heat Up and Potentially be Lower in Temperature

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Jetta, Beetle	2011-2016	All	All	All	All

## Technical Background

This is a normal characteristic of the vehicle as a result of the seat heating element being located below the Body Sense Mat for the passenger side air bag.

## Service

NA.

## Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2040360/3	6/27/17	Update to latest standard.
2040360/2	4/15/16	Update model year applicability.
2040360/1	4/10/15	Original publication.

© 2017 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.