

**On-car analysis list from September 14th, 2017  
please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Passat	13	3.6L (CDVB)	All	MIL-on P0420 and/or P0430	MIL-on P0420 and/or P0430 in the ECM <b>(untouched vehicles)</b>
	Golf Sportwagen (Alltrack only)	17	All	All	MIL-on P0463 and B103E1B	MIL-on P0463 and B103E1B stored <b>(untouched vehicles)</b>
	Jetta	17	1.4T (CZTA)	All	Fuel Gauge	Fuel gauge drops to empty with fault B103E1B <b>(untouched vehicles)</b>
<b>Chassis</b>	Jetta	17	All	All	MIL-on P0556	MIL-on P0556 in the ECM <b>(untouched vehicles)</b>
	Jetta	17	All	All	Rear Wheel Speed Sensor	ABS warning light with faults VAG00290 and/or VAG00287 in the ABS module <b>(untouched vehicles)</b>
<b>Body</b>	Passat	17	1.8T (CPRA)	All	Noise from Dash	Customer states noise from passenger side of dash <b>(untouched vehicles)</b> <b>(A/C line must be contacting right side frame rail)</b>
<b>Electrical</b>	Jetta	17	1.4T (CZTA)	All	MIL-on P068A	MIL-on P068A in the ECM <b>(untouched vehicles)</b>